

Engineering Geodesy I HS 2010

Exercise 2a: Application & Compiling

Goals:

- extend your own automatic deformation monitoring system
- create a graphical interface for your application
- compile it and create a stand alone application
- perform real time tracking

Tasks:

- 1) Type "guide" in the Matlab command line. Create Blank GUI (default).
- 2) Click on "Pushbutton" and then use the mouse to create a window for a button.
- 3) Double click on the newly created button "Push Button" → the property inspector opens up.
- 4) Change the property "String" from "Push Button" into "Angle Request". Change also the FontSize to e.g. 12. Close property Inspector
- 5) Adjust window size with the mouse.
- 6) Save Figure as "monitoring.fig" (this creates also monitoring.m)
- 7) open monitoring.m and add the name of your application `angle_request.m`, (e.g. http://www.geometh-data.ethz.ch/student/eg1/2010/02_deformation/angle_request.txt) at the end of the file (after "`function pushbutton1_Callback(hObject, eventdata, handles)`"), i.e. type "`angle_request;`". This line will be carried out each time the push button is pressed.
- 8) For preventing error messages at start-off, write a try-catch block around line 73:

```
try
varargout{1} = handles.output;
catch
end
```
- 9) Run monitoring.m

10) Add 2 functions to your application:

- a) open_port.m that defines and opens the serial com-port
- b) close_port.m for closing the com-port

Note that angle_request.m does not require the handling of the com-port anymore!

Note that the serial object has to be defined as a global variable in all files, type:

```
global s;
```

11) Add find_prism.m that lets the instrument find the next target.

12) type “mcc -m monitoring.m” to evoke the matlab compiler. Option “-m” creates a stand alone application: monitoring.exe, c-files (monitoring_main.c, monitoring_mcc_component_data.c) and the monitoring.mcr file.

13) Start monitoring.exe on any computer (include the mcr-files).

14) The figure properties can be changed during runtime directly in Matlab, e.g. type `set(gcf, 'String', 'done');` behind a function call for a callback in monitoring.m.

15) Create a new m-file small_menu.m with the following contents and run it:

```
function varargout = small_menu(varargin)

mea=uimenu('Label','&Measure');
ang=uimenu(mea,'Label','Angle Request','Callback','angle_request;');
return;
```

Add the functions: open_port, close_port, find_prism and coordinate request.

16) Download tracking.zip from the EG1 Website, extract the files and try to figure out what the Tracking_R.m file does.

Note:

If you use a 360° reflector, set at the instrument the prism settings: 5 Konfig, 2 Inst. Set., 1 EDM, → EDM type: Leica 360°. Alternatively, `send(serPort, '17008:3')` would set it automatically (3 = Leica 360° Prism).

A “+” at the top row indicates that the instrument is in lock-mode, a circle around it shows that the prism is locked.